



ANALISIS DE AGUA

POZO : LO6-19

INTERVALO : 8356'-8298' (Low. Basal Salina)

MUESTREO : 29.OCT.94

°API : 36 del Crudo Recuperado

	MUESTRA No. 1	MUESTRA No. 2	MUESTRA No. 3	MUESTRA No. 4	MUESTRA No. 5	MUESTRA No. 6
SP -GR	1.024	1.024	1.021	1.024	1.021	1.021
Cloruros (Titul.)	15620	18105	18460	17750	17927.5	17040
NaCl (Titul.)	25773	29873.25	30459	29287.5	29580.375	28116
Resistividad	0.25 @ 73°F	0.24 @ 73°F	0.24 @ 73°F	0.23 @ 73°F	0.24 @ 74°F	0.26 @ 73°F
NaCl (Tabla)	26000	26000	26000	27000	26000	25000
PH	8.64	9.60	8.65	9.72	9.61	8.74

LO6-20

LO7-16

RESISTIVIDAD

0.23 (73°F)

0.22 (73°F)

CLORUROS

15,975

17,040

Cl Na

27,000

POZO : LO6-19

INTERVALO : 7666'-7586' (Upp. Basal Salina)

Antes del Frac

MUESTREO : 29.OCT.94 (*)

HORA	MUESTRA No. 1 5:30 PM	MUESTRA No. 2 11:00 PM	MUESTRA No. 3 11:30 PM
SP -GR	1.024	1.021	1.021
Cloruros (Titul.)	18460	18105	18282.5
NaCl (Titul.)	30459	29873.25	30166.125
Resistividad	0.22 @ 82°F	0.23 @ 79°F	0.23 @ 81°F
NaCl (Tabla)	26000	26000	25500
PH	8.26	7.81	8.17

(*) Posiblemente del intervalo inferior